

L Number	Hits	Search Text	DB	Time stamp
-	0	electromigration with (measur\$4 or detect\$3) with (blech adj2 law)	USPAT; US-PGPUB	2003/08/06 14:43
-	141	electromigration with (measur\$4 or detect\$3)	USPAT; US-PGPUB	2003/08/06 14:43
-	91	(electromigration with (measur\$4 or detect\$3)) and length	USPAT; US-PGPUB	2003/08/06 14:43
-	21	(electromigration with (measur\$4 or detect\$3)) and ((detect\$3 or measure\$4)with length)	USPAT; US-PGPUB	2003/08/06 17:35
-	12468	determin\$3 or measure\$4 or detect\$3) with((critical or line or conductor or metal or wire)near3 length	USPAT; US-PGPUB	2003/08/06 17:37
-	0	(determin\$3 or measure\$4 or detect\$3) with((critical or line or conductor or metal or wire)near3 length) and (blech with law)	USPAT; US-PGPUB	2003/08/06 17:37
-	10	(determin\$3 or measure\$4 or detect\$3) with((critical or line or conductor or metal or wire)near3 length) and (blech	USPAT; US-PGPUB	2003/08/06 17:37
-	6729	((257/734,758) or (324/763,765,158.1,713)).CCLS.	USPAT; US-PGPUB	2003/08/07 10:35
-	22	((257/734,758) or (324/763,765,158.1,713)).CCLS.) and ((determin\$3 or detect\$3 or measure\$4 or test\$3) near3 ((critical or blech or line or wire)adj length))	USPAT; US-PGPUB	2003/08/07 10:41
-	1175	((determin\$3 or detect\$3 or measure\$4 or test\$3) near3 ((critical or blech or line or wire or conductor)adj length))	USPAT; US-PGPUB	2003/08/07 10:42
-	33	(((determin\$3 or detect\$3 or measure\$4 or test\$3) near3 ((critical or blech or line or wire or conductor)adj length))) and (electromigration or EM)	USPAT; US-PGPUB	2003/08/07 11:17
-	1	("6320391").PN.	USPAT; US-PGPUB	2003/08/07 11:18
-	1	((("6320391").PN.) and length	USPAT; US-PGPUB	2003/08/07 11:40
-	1	("5900735").PN.	USPAT; US-PGPUB	2003/08/07 11:40
-	0	((("5900735").PN.) and voltage	USPAT; US-PGPUB	2003/08/07 11:40
-	1	((("5900735").PN.) and (voltage or potential)	USPAT; US-PGPUB	2003/08/07 11:40